



Sketch view of the servery with the serving doors open. Adapting the existing panelling will be difficult to achieve and the panels will need to be framed and this not align with the fixed set above. It should also be noted that in each of the servery options, a secondary fire shutter may be required to separate the servery from the main body of the church in order for the exit route to the south door to be maintained.