

Installation photographs of the organ at Steyning Parish Church



Photograph of the new organ, as first installed in 1968 under the tower arch  
(before the construction of vestries under the tower).

1 of 4

Installation photographs of the organ at Steyning Parish Church



Photograph of the enlarged organ in 1983  
(after the construction of new two-storey vestries under the tower).


2 of 4

Installation photographs of the organ at Steyning Parish Church



Victorian photograph of the west end of the church before the construction of the new tower arch in 1881 (showing the aisle galleries before their removed in 1906).

Installation photographs of the organ at Steyning Parish Church



Handwritten notes on the rear of the Victorian photograph, opposite.